

SPARE PARTS KIT ET MA-R 3



Sight glass
(08.2205.00)




Gasket FKM
(30.0225.00)


Gasket FKM
(30.0214.80)



Active carbon
(33.0507.00)



Filter unit
(08.0002.81)



Foam disc
(33.0402.00)



Gasket FKM
(30.0219.80)



O-ring FKM
(30.0163.00)



GIEBEL Xdry needed per Adsorber:
- Adsorber MA-R / RV 3M: 0,85 KG / 1.87 LB
- Adsorber MA-R / RV 3L: 1,45 KG / 3.2 LB



GIEBEL Xdry
sold separately



GIEBEL Adsorber®
...setting standards in aeration drying!

				Date	Name	Weight (kg/lb): 0.2 / 0.44
				Created 01.12.2021	daniel.zinic	Naming:
				Released 08.01.2026	daniel.zinic	Spare Parts Kit
				GIEBEL www.giebel-adsorber.com info@gf-dry.com		ET_MA-R_3_F_P3_C
						Article number:
				Observe protection note ISO 16016		07.0003.26
Rev	Changes	Date	Name			Status approved
						Scale
						Format A4
						Sheet / of
						1 / 1